

# Release Note for Vigor3912 Series

Firmware Version:	4.3.6.1
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	Vigor3912, Vigor3912S

## New Features

- None.

## Improvement

- Improved: Improve the Web GUI Security.
- Improved: Modify the description for the Fast NAT check box on NAT>>Fast Routing/NAT.
- Corrected: An issue with failure to use the new created Google API via Hotspot.
- Corrected: An issue is that the Vigor router (HA slave with WCF enabled) constantly rebooted.
- Corrected: An issue with the lack of the WAN interface setting field on VPN>>VPN Matcher Setup.
- Corrected: An issue with the hotspot HTTPS redirection error by the HTTPS management port being set as non-default.
- Corrected: An issue with the URL filter failed to block HTTPS websites when TLS 1.3 hybridized Kyber was enabled.
- Corrected: An issue with the WUI of Objects Setting>>SMS/Mail Service Object lost connection temporarily after clicking “Send a Test Message”.
- Corrected: An issue that the IPsec Peer Identity profile still appeared and was selected on the remote dial-in profile, even if it was deleted or renamed.

## Known Issue

- None.