Release Note for VigorConnect

Software Version:	1.8.1
Release Type:	Normal - Upgrade recommended when convenient
Applied System:	Windows 7, 8, 10, 11 / Linux / Raspberry Pi / Docker
Applied Models:	VigorAP 1000C, 1060C, 802, 810, 903, 906, 912C, 918R Series, 920R Series, 960C VigorSwitch P2500/G2500, P2280/G2280, P2280x/G2280x, P2100/G2100, P2121/G2121, P1280/G1280, P1085/G1085, G1080, P1092, FX2120, PQ2200xb/Q2200x, P1282/G1282, and Q2121x/PQ2121x.

VigorConnect is a software which provides centralized AP management and switch management for TR-069 based devices. VigorConnect has device status, monitor status of devices, or perform scheduling tasks such as firmware upgrade, configuration backup/restore and parameter profile for mass deployment of the managed devices.

New Features

- Support VigorAP 906.

Improvement

- Corrected: An issue with failure to get the software system name.
- Corrected: An issue with failure to manage more than 2 Netflow routers.
- Corrected: An issue with no CPE response after performing the discovery job.
- Corrected: An issue with Web UI troubles while registering to VigorACS for the first time.
- Corrected: An issue with failure to search VigorAP (as a Mesh Node) via the function of Discover New Devices.
- Corrected: An issue with displaying the same VigorSwitch frequently on Configuration VLAN Setting>>Graphic View.

Known Issue

- An issue that viewing Flow with FireFox (HTTPS) would block illegal HTTPS certificate issued by Grafana.