

Release Note for Vigor3912 Series

Firmware Version:	4.4.3.8
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	Vigor3912, Vigor3912S

New Features

- None.

Improvement

- Corrected: An issue with the firewall malfunctioning.
- Corrected: An issue that the DHCP Relay forwarded Discover packets to only one DHCP server on LAN 10.
- Corrected: An issue that the BFP number on dashboard was inconsistent with the BFP number on the Firewall.

Known Issue

- None.