

Release Note for VigorSwitch PX2060

Firmware Version:	2.9.12
Loader Version:	3.5.5
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	VigorSwitch PX2060

New Features

- None.

Improvement

- Improved: Strengthened Web/CGI security and addressed multiple security issues (CVE-2026-71917, CVE-2026-71919 to CVE-2026-71922, CVE-2026-71929 to CVE-2026-71933, and CVE-2026-71935 to CVE-2026-71943).

Known Issue

- None.

Note

- STP (Spanning Tree Protocol) is enabled by default starting from firmware version 2.9.8, which may result in a slightly longer link-up time for ports.